

Matrox MC-100

Release Notes

August 11, 2014



Y11197-401-0130

Trademarks

Matrox Electronic Systems Ltd. Matrox®

All other nationally and internationally recognized trademarks and tradenames are hereby acknowledged.

Copyright © 2014 Matrox Electronic Systems Ltd. • All rights reserved.

Disclaimer Matrox Electronic Systems Ltd. reserves the right to make changes in specifications at any time and without notice. The information provided by this document is believed to be accurate and reliable. However, no responsibility is assumed by Matrox Electronic Systems Ltd. for its use; nor for any infringements of patents or other rights of third parties resulting from its use. No license is granted under any patents or patent rights of Matrox Electronic Systems Ltd.

Unauthorized recording or use of broadcast television programming, video tape, or other copyrighted material may violate copyright laws. Matrox Electronic Systems Ltd. assumes no responsibility for the illegal duplication, use, or other acts that infringe on the rights of copyright owners.

Matrox Electronic Systems Ltd.

1055 St. Regis Blvd., Dorval, Quebec, Canada H9P 2T4

Tel: (514) 685-2630 Fax: (514) 685-2853 World Wide Web: www.matrox.com

Contents

About these release notes	1
Visit our website for the latest downloads	1
What's new in this release	1

Your notes

About these release notes

These release notes provide important information applicable to Matrox MC-100 version 1.3. This information supplements the *Matrox MC-100 User Guide*, which is provided in PDF format in the Matrox MC-100 Support section of our website at www.matrox.com/video/support.

Visit our website for the latest downloads

To ensure that you have the latest hardware update for your MC-100, as well as the latest documentation, check the MC-100 Support section of our website at www.matrox.com/video/support.

What's new in this release

Matrox MC-100 version 1.3 provides the following new features:

- New functionality for the loss-of-signal switcher, which enables MC-100 to automatically switch to a different channel if it detects a signal loss on a main channel.
- A bug fix for the HDMI output that corrects the audio mapping in order to properly output 5.1 surround sound.

Your notes



www.matrox.com/video